



CNC TOOL STORAGE PRODUCTS

LATHE SCOOT - ASSEMBLY INSTRUCTIONS



- | | |
|-------------------------------|-----------------------|
| 1 : Bottom Tray support(s) | 13 : Handle Assembly |
| 2 : Bottom Wheel tray | 14 : Pegboard |
| 3 : Castors | 15 : Utility Tray |
| 4 : Left side cover | 16 : Mini Bench Model |
| 5 : Right side cover | 17 : Support bracket |
| 6 : Middle tray | 18 : Collet Organizer |
| 7 : Left Bench Support | |
| 8 : Right Bench Support | |
| 9 : Bench support tray | |
| 10 : Pegboard Support(s) | |
| 11 : Quick Change Collet tray | |
| 12 : Shank Holder | |



Please turn over for more info

CNC TOOL STORAGE PRODUCTS

LATHE SCOOT - ASSEMBLY INSTRUCTIONS



8 : Right Bench Support
15 : Utility Tray
16 : Mini Bench Model
17 : Support brackets
18 : Collet Organizer

- Attach the bottom tray supports (1) to the bottom wheel tray (2)
- Attach the castors (3) to the bottom wheel tray (2) and tighten fully
- Attach the left (4) / right (5) side covers to the bottom wheel tray (2) , but do not fully tighten them at this stage
- Attach the middle tray (6) and secure with the nuts and bolts
- Attach the left (7) / right (8) bench supports, as well as the bench support tray (9)
- Attach the pegboard supports (10) to the left / right side covers, but only install the bottom 2 nuts per support at this stage
- Attach the quick change collet tray (11) and shank holder (12)
- Attach the handle assembly (13) and pegboard (14)
- Attach the utility tray (15) to the back of the pegboard
- Assemble and attach the mini bench model (16)
- Attach the organizer support brackets (17)
- Assemble and attach the collet organizer (18)
- Tighten all nuts and bolts